



RubbaFIX[®]

CASE HISTORY

GROOVE REPAIR


RESULT

- **6 metre split in belt repaired.**
- **Belt returned to service in 1 hour.**




DESCRIPTION

- **Split skived into 20mm groove using knife and prepped with wire to allow for maximum surface adhesion.**



SOLUTION

- Groove filled with RubbaFIX[®] repair compound using the MELTA[®] Pro Applicator.



SOLUTION

Repair cut flush with belt using flat knife to avoid damage.



SOLUTION

- **Repair completed using an estimated 600g of product in 1 hour including cure time.**



SUMMARY

INDUSTRY : Iron Ore

PRODUCT : RubbaFIX®

PLANT : Port Facility

LOCATION : Pilbara Region, Western Australia

DATE : August 2014

SUMMARY : 6 metre split repair

ROI : 4 hours cure time saved compared to traditional two-part products

CONTACT US

Let us help you find out how our rubber products can improve your operations, and save you time and money.

Toll free	: 1800 352 228
International	: +61 2 8853 3000
Email	: info@rubbafix.com.au
Website	: www.rubbafix.com.au